



Cactus Approved Sub-Supplier List

Name	Approved Process	Address
Houston Plating & Coatings	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	1301 Georgia Street South Houston, TX 77587
Webco Coating Inc	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	1708 E Butcher Switch Road Lafayette, LA 70507
Plas-Tech Coatings Inc	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	1000 North 5 Points Road West Chester, PA 19380
Alpha Coating Systems, Inc. / Don's Grinding & Lapping Service, Inc.	CST-807 Tungsten Carbide Hardfacing	8700 Tweed Drive Houston, TX 77061
Metal Coating Corporation	CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	3700 Dunvale Road Houston, TX 77063
Progressive Metal Services	CST-801 Salt Bath Nitriding QPQ CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	4117 Meadow Lane Bossier City, LA 71111
S+S Industries	CST-800 Copper Plating CCS-608 Xylan 1070 CCS-609 Xylan 1052 CCS-610 Xylan 1014	5614 Nunn Street Houston, TX 77087
Specialty Heat Treat Inc	Heat Treatment per Cactus Wellhead Specs	11307 West Little York Houston, TX 77041
LST Heat Treating	CHT-100 Gas Carburizing Heat Treatment per Cactus Wellhead Specs	8 Gum Valley Circle Longview, TX 75602
Bodycote Thermal Processing	Heat Treatment per Cactus Wellhead Specs	116 Southpark Road Lafayette, LA 70508
Coleman Heat Treating Inc	Heat Treatment per Cactus Wellhead Specs	2500 West Main Street Jacksonville, AR 72076
Houston Heat Treat	Heat Treatment per Cactus Wellhead Specs	13802 Chrisman Road Houston, TX 77039
K & D Heat Treat	Heat Treatment per Cactus Wellhead Specs	2115 Humble Westfield Houston, TX 77073
Lark Heat Treating	Heat Treatment per Cactus Wellhead Specs	6640 Mayard Road Houston, TX 77041
Magnum Metal Treating	Heat Treatment per Cactus Wellhead Specs	4400 North Frazier Street Conroe, TX 77039
Lone Star Heat Treating	Heat Treatment per Cactus Wellhead Specs	3939 Blaffer Street Houston, TX 77026
SEI Heat Treat	Heat Treatment per Cactus Wellhead Specs	6910 Fulton Houston, TX 77022
Total NDT	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material CNT-007 Radiography API 6A Ultrasonic - Welds	104 Valentine Street Longview, TX 75604
LTD NDT Service, LLC	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	2508 S Ann Arbor Avenue Oklahoma City, OK 73128
Accu-Test Labs	CNT-002 Visible Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material Laboratory Metallurgical Testing	6722 Guhn Road Houston, TX 77040
Common Sense Inspection Inc	CNT-004 Magnetic Particle Testing	1295 East 1750 South Vernal, UT 84078



Cactus Approved Sub-Supplier List

Name	Approved Process	Address
Acuren Inspection	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing	405 N Eastman Road Longview, TX 75601
Bilfinger Inc	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	510 LaFlamme Road Broussard, LA 70518
P & B Testing Inc	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material Laboratory Metallurgical Testing	6645 W Tidwell Road Houston, TX 77092
Peak NDT Solutions	CNT-004 Magnetic Particle Testing	515a Verot School Road Lafayette, LA 70508
Sound NDT Solutions	CNT-004 Magnetic Particle Testing	9672 Pozos Lane Conroe, TX 77303
Pro-Mag Inspection	CNT-004 Magnetic Particle Testing	173 Trinity Lane Gray, LA 70359
Quality Concepts	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material CIR-002 Hardness Testing Laboratory Metallurgical Testing	7825 Hillmont Street Houston, TX 77040
RCI NDT	CNT-002 Visible Liquid Penetrant Testing	2771 FM 3081 Willis, TX
Rite Inspection Services	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	8484 Breen Drive Houston, TX 77064
RSC Inspection Service	CNT-004 Magnetic Particle Testing	106 Capital Boulevard Houma, LA 70360
TEAM Industrial Servies	CNT-002 Visible Liquid Penetrant Testing CNT-003 Fluorescent Liquid Penetrant Testing CNT-004 Magnetic Particle Testing CNT-005 Ultrasonic Testing Wrought Material	3875 West Cardinal Drive Beaumont, TX 77705
Weldon NDE	CNT-005 Ultrasonic Testing Wrought Material	504 Hohldale Houston, TX 77091